Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9

| REFERENCE POINT | a 1 | a2 | а3 | a n |
|-----------------|--|---|--|-------------|
| REFERENCE VALUE | a1p | а2р | аЗр | апр |
| MARGIN | K | ᅩ | -× | ~ |
| MEASURED VALUE | alP | a2P | а3Р | NO DATA |
| COMPARISON | MEASURED VALUE - REFERENCE VALUE <k< td=""><td> MEASURED VALUE MEASURED VALUE MEASURED VALUE - REFERENCE VALUE <k -="" k="" reference="" value <="" value <k=""></k></td><td> MEASURED VALUE - REFERENCE VALUE ≥k</td><td></td></k<> | MEASURED VALUE MEASURED VALUE MEASURED VALUE - REFERENCE VALUE <k -="" k="" reference="" value <="" value <k=""></k> | MEASURED VALUE - REFERENCE VALUE ≥k | |
| OPERATION | CONTINUE | CONTINUE | STOP CONTROL | |